

List of PC Card Adapters supported by CardWare 7.00

State of November 5, 2012.

I. PCIC and compatible adapters (including CardBus)

I.1. Acer Labs

1. Acer Labs M5235

I.2. Cirrus Logic Adapters

2. Cirrus Logic CL-PD6710
3. Cirrus Logic CL-PD6720
4. Cirrus Logic CL-PD6722 (rev. 0)
5. Cirrus Logic CL-PD6722 (rev. 1)
6. Cirrus Logic CL-PD6729 (Rev A)
7. Cirrus Logic CL-PD6729 (Rev B)
8. Cirrus Logic CL-PD6729 (Rev C)
9. Cirrus Logic CL-PD6729 (Rev E)
10. Cirrus Logic CL-PD6730 (Rev A)
11. Cirrus Logic CL-PD6730 (Rev B)
12. Cirrus Logic CL-PD6832 (CardBus)

I.3. DataBook

13. DataBook DB87144 (CardBus)

I.4. ENE Technology Inc.

14. ENE Technology CB-1211 (CardBus)
15. ENE Technology CB-1225 (CardBus)
16. ENE Technology CB-1410 (CardBus)
17. ENE Technology CB-1420 (CardBus)
18. ENE Technology CB-710 (CardBus)
19. ENE Technology CB-720 (CardBus)

I.5. IBM Adapters

20. IBM Stinger
21. IBM TOMCAT
22. IBM ThinkPad 750
23. IBM KING

I.6. Intel Adapters

24. Intel 82365SL A step or compatible
25. Intel 82365SL B step or compatible
26. Intel 82365SL C step or compatible
27. Intel PHIC
28. Intel PPEC (PCI)

I.7. LSI Logic

29. LSI Logic HT27

I.8. Omega Micro

30. Omega Micro 82C722GX

I.9. O2Micro

- 31. O2Micro OZ6722
- 32. O2Micro OZ6729 (PCI)
- 33. O2Micro OZ6730 (PCI)
- 34. O2Micro OZ6812 (CardBus)
- 35. O2Micro OZ6832 (CardBus)
- 36. O2Micro OZ6833 (CardBus)
- 37. O2Micro OZ6836 (CardBus)
- 38. O2Micro OZ6860 (CardBus)
- 39. O2Micro OZ6912 (CardBus)
- 40. O2Micro OZ6922 (CardBus)
- 41. O2Micro OZ6933 (CardBus)
- 42. O2Micro OZ711E0 (CardBus)
- 43. O2Micro OZ711E1 (CardBus)
- 44. O2Micro OZ711EC1/M1 (CardBus)
- 45. O2Micro OZ711EC1 (CardBus)
- 46. O2Micro OZ711M1 (CardBus)
- 47. O2Micro OZ711MP1MS1 (CardBus)
- 48. O2Micro OZ711EZ1/MZ1 (CardBus)
- 49. O2Micro O2_OZ711SP1 (CardBus)
- 50. O2Micro OZ711E2 (CardBus)
- 51. O2Micro OZ OZ711M2 (CardBus)
- 52. O2Micro OZ6933E
- 53. O2Micro OZ711M3 (CardBus)
- 54. O2Micro O2_OZ711MP3MS3 (CardBus)

I.10. PicoPower

- 55. PicoPower 82C786 (PCMCIA Plus)

I.11. Ricoh

- 56. Ricoh RF5C266
- 57. Ricoh RF5C366
- 58. Ricoh RF5C269
- 59. Ricoh RF5C369
- 60. Ricoh R5C475 (CardBus)
- 61. Ricoh R5C476 (CardBus)
- 62. Ricoh R5C477 (CardBus)
- 63. Ricoh R5C478 (CardBus)
- 64. Ricoh R5C475II (CardBus)
- 65. Ricoh R5C476II (CardBus)
- 66. Ricoh R5C478II (CardBus)
- 67. Ricoh R5C485 (CardBus)
- 68. Ricoh R5C486 (CardBus)
- 69. Ricoh R5C522 (CardBus)
- 70. Ricoh R5C551 (CardBus)
- 71. Ricoh R5C554 (CardBus)
- 72. Ricoh R5C803 (CardBus)
- 73. Ricoh R5C811 (CardBus)
- 74. Ricoh R5C812 (CardBus)
- 75. Ricoh R5C841 (CardBus)
- 76. Ricoh R5C842 (CardBus)
- 77. Ricoh R5C843 (CardBus)
- 78. Ricoh R5C847 (CardBus)
- 79. Ricoh R5C853 (CardBus)

I.12. Texas Instruments

- 80. Texas Instruments PCI1030 (PCI)
- 81. Texas Instruments PCI1031 (CardBus)
- 82. Texas Instruments PCI1050 (PCI)
- 83. Texas Instruments PCI1130 (CardBus)
- 84. Texas Instruments PCI1131 (CardBus)
- 85. Texas Instruments PCI1210 (CardBus)
- 86. Texas Instruments PCI1211 (CardBus)
- 87. Texas Instruments PCI1220 (CardBus)
- 88. Texas Instruments PCI1221 (CardBus)
- 89. Texas Instruments PCI1225 (CardBus)
- 90. Texas Instruments PCI1250 (CardBus)
- 91. Texas Instruments PCI1250A (CardBus)
- 92. Texas Instruments PCI1251A (CardBus)
- 93. Texas Instruments PCI1251B (CardBus)
- 94. Texas Instruments PCI1410 (CardBus)
- 95. Texas Instruments PCI1420 (CardBus)
- 96. Texas Instruments PCI1450 (CardBus)
- 97. Texas Instruments PCI1451 (CardBus)
- 98. Texas Instruments PCI1510 (CardBus)
- 99. Texas Instruments PCI1515 (CardBus)
- 100. Texas Instruments PCI1520 (CardBus)
- 101. Texas Instruments PCI1620 (CardBus)
- 102. Texas Instruments PCI4410 (CardBus)
- 103. Texas Instruments PCI4450 (CardBus)
- 104. Texas Instruments PCI4451 (CardBus)
- 105. Texas Instruments PCI4510 (CardBus)
- 106. Texas Instruments PCI4512 (CardBus)
- 107. Texas Instruments PCI4515 (CardBus)
- 108. Texas Instruments PCI4520 (CardBus)
- 109. Texas Instruments PCI6411 (CardBus)
- 110. Texas Instruments PCI6412 (CardBus)
- 111. Texas Instruments PCI6420 (CardBus)
- 112. Texas Instruments PCI6421 (CardBus)
- 113. Texas Instruments PCI6515 (CardBus)
- 114. Texas Instruments PCI6611 (CardBus)
- 115. Texas Instruments PCI6612 (CardBus)
- 116. Texas Instruments PCI6620 (CardBus)
- 117. Texas Instruments PCI6621 (CardBus)
- 118. Texas Instruments PCI7410 (CardBus)
- 119. Texas Instruments PCI7411 (CardBus)
- 120. Texas Instruments PCI7412 (CardBus)
- 121. Texas Instruments PCI7415 (CardBus)
- 122. Texas Instruments PCI7420 (CardBus)
- 123. Texas Instruments PCI7421 (CardBus)
- 124. Texas Instruments PCI7510 (CardBus)
- 125. Texas Instruments PCI7610 (CardBus)

- 126. Texas Instruments PCI7611 (CardBus)
- 128. Texas Instruments PCI7620 (CardBus)
- 130. Texas Instruments PCI8412 (CardBus)

- 127. Texas Instruments PCI7612 (CardBus)
- 129. Texas Instruments PCI7621 (CardBus)

I.13. Toshiba

- 131. Toshiba ToPIC
- 133. Toshiba ToPIC95M (CardBus)
- 135. Toshiba ToPIC100 Nova 100 (CardBus)
- 137. Toshiba ToPIC100 Suez (CardBus)
- 139. Toshiba ToPIC100 Sydney99 (CardBus)

- 132. Toshiba ToPIC95 (PCI adapter)
- 134. Toshiba ToPIC97 (CardBus)
- 136. Toshiba ToPIC100 Nova 200 (CardBus)
- 138. Toshiba ToPIC100 Donau (CardBus)
- 140. Toshiba ToPIC100 Nova 100SE (CardBus)

I.14. Vadem

- 141. Vadem chip VG-365
- 143. Vadem chip VG-468
- 145. Vadem Chip VG-469 (rev. 8D)

- 142. Vadem chip VG-465
- 144. Vadem Chip VG-469

I.15. VLSI

- 146. VLSI VL82C146

II. TCIC and compatible adapters

II.1. DataBook

- 147. DataBook DB86081
- 149. DataBook DB86082A
- 151. DataBook DB86072
- 153. DataBook DB86084
- 155. DataBook DB86183
- 157. DataBook DB86501

- 148. DataBook DB86082
- 150. DataBook DB86082B
- 152. DataBook DB86272
- 154. DataBook DB86084A
- 156. DataBook DB86184

II.2. Mitsubishi

- 158. Mitsubishi MB86301

III. Express-2-PCMCIA Adapters

III.1. Duel Systems / Quatech Inc.

- 159. PCD-X/XC34

III.2. Delock.

- 160. Express Card /34

IV. USB-2-PCMCIA Adapters

IV.1. CSM GmbH

- 161. OmniDrive USB2 LF

V. Notes:

- Note 1:** Delock Express Card / 34 and CSM GmbH OmniDrive USB2 LF are not supported in any CardWare release prior to November 4th, 2012.
- Note 2:** Duel Systems / Quatech Inc. PCD-X/XC43 is not supported in any CardWare release prior to June 25th, 2012:
- Note 3:** CardWare for Windows 98/ME, CardWare for Windows 2000/XP and Server 2003 and CardWare for Windows Vista rely on Windows Services for PC Card adapter detection. Therefore list of supported PC Card adapters in those OS is defined by Microsoft. Please pay attention that TCIC support by Microsoft is not complete and will not work.
- Note 4:** Ricoh R5C477/485/486/522/551/554/803/811/812/841/842/843/847/853 and O2Micro OZ6922, OZ711MP1/MS1, OZ711EZ1/MZ1, OZ711SP1, OZ6933E, OZ711MP3/MS3 are not supported in any CardWare release prior to September 22nd, 2007
- CardWare for Windows NT 7.00.009 and prior
 - CardWare for DOS/Windows 7.00.008 and prior
 - OS/2 Socket Services driver released prior to Sep 22nd, 2007.
- Note 5:** Texas Instruments TI4512/6412/6612/7412/7612/8412 are not supported in any CardWare release prior to Jun 1st, 2006
- CardWare for Windows NT 7.00.008 and prior
 - CardWare for DOS/Windows 7.00.008 and prior
 - OS/2 Socket Services driver released prior to Jun 1st, 2006.
- Note 6:** Texas Instruments TI1515/4515/6515/7515 are not supported in any CardWare release prior to Feb 02, 2005
- CardWare for Windows NT 7.00.005 and prior
 - CardWare for DOS/Windows 7.00.005 and prior
 - OS/2 Socket Services driver released prior to Aug 07, 2004.
- Note 7:** Texas Instruments TI6411/6421/6611/6621/7411/7421/7611/7621 are not supported in any CardWare release prior to Aug 07, 2004
- CardWare for Windows NT 7.00.004 and prior
 - CardWare for DOS/Windows 7.00.004 and prior
 - OS/2 Socket Services driver released prior to Aug 07, 2004.
- Note 8:** Texas Instruments TI6420/6620 are not supported in any CardWare release prior to Jul 18th, 2003
- CardWare for Windows NT 6.00.041 and prior
 - CardWare for DOS/Windows 6.00.014 and prior
 - OS/2 Socket Services driver released prior to Jul 18th, 2003.
- Note 9:** Texas Instruments TI7420, 7620 are not supported in any CardWare release prior to May 27th, 2003
- CardWare for Windows NT 6.00.040 and prior
 - CardWare for DOS/Windows 6.00.014 and prior
 - OS/2 Socket Services driver released prior to May 27th, 2002.



APSoft
Am Wald 6
84437 Reichertsheim
Germany
Phone: +49 (8073) 9280
Fax: +49 (8073) 9275

- Note 10:** Texas Instruments TI45x0, 7x10 are not supported in any CardWare release prior to April 10th, 2003
- CardWare for Windows NT 6.00.039 and prior
 - CardWare for DOS/Windows 6.00.014 and prior
 - OS/2 Socket Services driver released prior to April 10th, 2002.
- Note 11:** Texas Instruments TI1510, 1520 are not supported in any CardWare release prior to November 12th, 2002
- CardWare for Windows NT 6.00.037 and prior
 - CardWare for DOS/Windows 6.00.013 and prior
 - OS/2 Socket Services driver released prior to November 12th, 2002.
- Note 12:** ENE Technology CB-710 and CB-720, O2Micro 6812, 6836, 6860, 6933, TI4510 adapters are not supported in any CardWare release prior to September 21, 2002:
- Note 13:** ENE Technology adapters CB-1211, CB-1225, CB-1410 and CB-1420 are not supported in any CardWare release prior to August 17th, 2002: